

December 10, 2013

Attn: TIMCO Engineering Inc.

849 N.W. State Road 45

P.O. Box 370

Newberry, Florida 32669

FCC ID: 2AA8Y-416015 IC : 11497A-416015

To Whom It May Concern:

BioMérieux S.A., declare that the differences between models 416013, 416014 and 416015 are for the presence of a screen and the number of connector for sensors. Radio is strictly the same.

Model	Number of connector	Screen
416013	1	No
416014	2	Yes
416015	4	Yes

Sincerely,

Johan DEVELON R&D Instruments Manager