Test report No. : 10186747H-A-R2

Page : 22 of 23

FCC ID : 2AA9A-D4600-PRINTER
Issued date : February 25, 2014
Revised date : May 14, 2014

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10186747H-A-R2

Page : 23 of 23

FCC ID : 2AA9A-D4600-PRINTER
Issued date : February 25, 2014
Revised date : May 14, 2014

Radiated emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124