


Report No: CCIS13120055001

7 Test Setup Photo

Radiated spurious emission:






Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366



Report No: CCIS13120055001

Conducted Emissions



Project No.: CCIS131200550RF