

vivint com info@vivint com 800 216 5232 **United States** 4931 North 300 West Provo UT 84604 Canada 3030 9th St SE Calgary AB T2G 3B9 651 450 4853

To Whom It May Concern,

Vivint understands that sr1410 device operates only in 40 MHz bandwidth mode, and hence channel 132 which was shown in the GUI will be removed.

Although the underlying radio software never used the channels in the TDWR band, the GUI implied that TDWR was transgressed, which we did not.

To remove any misinterpretation, Vivint attests herewith, that production software will not display that choice in the GUI.

Sincerely,

Venkat Kalkunte

VP Of Engineering

Vivint Inc.