

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01







FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version : Rev. 01







REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A7

Report Version

: Rev. 01


Report No.: FR512311AD




FCC Test Report

Report No.: FR512311AD

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A5 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report

Report No.: FR512311AD

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01







EUT took a close view



EUT took a close view

SPORTON INTERNATIONAL INC. Page No. : A7 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01