Test Report No : 10334913S

APPENDIX 3: Photographs of test setup

Conducted emission






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401


Test Report No : 10334913S

Radiated emission



Rear 9kHz-30MHz





UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test Report No : 10334913S

Pre-check of the worst position

Transmitter



Antenna X-axis



Y-axis



Y-axis







UL Japan, Inc. **Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile +81 463 50 6401