


Report No: CCIS13050015703

Test Setup Photo

Radiated Spurious Emission






Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366



Report No: CCIS13050015703



8 EUT Constructional Details

Reference to the test report No. CCIS13050015701

-----End of report-----

Telephone: +86 (0) 755 23118282 Fax: +86 (0) 755 23116366