


Test Photos Appendix F

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F4

Report No.

: 6N1731



Test Photos Appendix F



Side view

 SPORTON INTERNATIONAL INC.
 Page No.
 : F2 of F4


 TEL: 886-3-327-3456
 Report No.
 : 6N1731

FAX: 886-3-327-0973




Test Photos Appendix F

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F3 of F4 Report No. : 6N1731



Test Photos Appendix F

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F4 of F4
Report No. : 6N1731