


11. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT POE SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT AC MAINS SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






POWERLINE CONDUCTED EMISSIONS MEASUREMENT POE SETUP





POWERLINE CONDUCTED EMISSIONS MEASUREMENT AC MAINS SETUP





END OF REPORT