

Report No.: FR561709

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AAES-POP2015 Page Number : B1 of B2 Report Issued Date: Sep. 01, 2015 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0




Report No.: FR561709

<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AAES-POP2015 Page Number : B2 of B2
Report Issued Date : Sep. 01, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0