


Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A2

Report Version


: Rev. 01

Report No.: FR3N1937




FCC Test Report

Radiated Test



Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A2

Report No.: FR3N1937

Report Version : Rev. 01