



## 4.6 Test Photographs



Front View



Rear View

Tel:886-2-2655-8100 Fax:886-2-2655-8200

Issued date : Jun. 24, 2013


Report No.: TEFA1305106

Page No. : 15 of 41


FCC ID : 2AAIVHVC-50X



## 5.8 Test Photographs (30MHz ~ 1GHz)



Front View



Rear View

Tel:886-2-2655-8100 Fax:886-2-2655-8200

Issued date : Jun. 24, 2013


Report No.: TEFA1305106

Page No. : 28 of 41


FCC ID : 2AAIVHVC-50X



## 5.9 Test Photographs (1GHz ~ 25GHz)



Front View



Rear View

Cerpass Technology Corp.

Tel:886-2-2655-8100 Fax:886-2-2655-8200

Issued date : Jun. 24, 2013

Report No.: TEFA1305106

Page No. : 29 of 41

FCC ID : 2AAIVHVC-50X