


## Report No.: FA382044

## Appendix D. SAR Test Setup Photos



**Right Cheek** 


**Right Tilted** 







Left Tilted







Back, Test Separation 1.5 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AAL8- GC641127 Page Number : D1 of D1
Report Issued Date : Mar. 06, 2014
Report Version : Rev. 01