Report No. : T130530S01
Page \_\_\_1\_\_of \_\_\_14





Report No.: T130530S01 Page \_\_\_2 of \_\_\_14






VOIP processor

Report No.: T130530S01 Page 3 of 14








SDRAM for VOIP processor


Report No. : T130530S01
Page \_\_4\_\_of \_\_14






Page <u>5</u> of <u>14</u>






Crystal

Report No. : T130530S01
Page \_\_6\_\_of \_\_14\_\_




Ethernet phy




SPI flash for PLC Transceiver


Report No. : T130530S01
Page \_\_\_7 \_\_of \_\_\_14



SPI flash for Wifi SOC





Page <u>8</u> of <u>14</u>



Ethernet phy on VOIP Module


Crystal







Wifi SOC


Page <u>10</u> of <u>14</u>






Report No.: T130530S01 Page 11 of 14






Page 12 of 14



Report No.: T130530S01 Page 13 of 14





Report No. : T130530S01 Page <u>14</u> of <u>14</u>

