Correspondence by Project

Project Number:

1217550913

Correspondence Number	Memo
2AAMM581711-1	1) The user manual provides an incomplete FCC statement. Please provide a corrected user manual. A corrected User Manual has been provided. 2) The block diagrams provided show the availability of Ethernet connections, however this configuration was not tested. Please clarify and provide new block diagrams if appropriate. A corrected block diagram has been provided. 3) The schematics provided do not seem to be complete and seem to be missing components. Also, some schematics seem to be incorrect when compared to the photographs. Please provide corrected and complete schematics. Corrected schematics have been provided and an acceptable alternative to the missing schematics has been provided.

1 of 1 5/1/2014 11:30 AM