

RFID-Registration

HistoCore SPECTRA CV

 $RFID\text{-}Registration\ HistoCore\ SPECTRA\ CV}$

Order-No.: 14 0514 89998 RevA

Always keep this information with the instrument. Read carefully before working with the instrument.

Table of Contents

RFID-Registration for the United States of America and Canada......2

For HistoCore SPECTRA CV

RFID-Registration for the United States of America and Canada



Symbol on the Identification Label:



FCC ID: 2AAPD-SPECTRACV01 IC: 12028A-SPECTRACV01

Title of Symbol:

FCC-Approved Equipment

Description:

This device complies with Part 15 of the FCC Rules and with Industry Canada licence-exempt RSS standard(s).

Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes:

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

RFID-Registration for the United States of America and Canada (Continued)

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Changes or modifications made to this equipment not expressly approved by Leica Biosystems Nussloch GmbH may void the FCC authorization to operate this equipment.

For HistoCore SPECTRA CV 3

www.LeicaBiosystems.com



Leica Biosystems Nussloch GmbH Heidelberger Straße 17-19 D- 69226 Nussloch

Tel.: +49 - (0) 6224 - 143 0 Fax: +49 - (0) 6224 - 143 268 Web: www.LeicaBiosystems.com