

Appendix A. Test Photos

Report No. : FR3N2813-01

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Report No. : FR3N2813-01

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.

: A2 of A5

Report Version

: Rev. 01



CC Test Report No. : FR3N2813-01



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz




Report No. : FR3N2813-01

: A4 of A5

: Rev. 01

FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973




FCC Test Report No.: FR3N2813-01

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version

: Rev. 01