Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973



1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A5

Report Version

: Rev. 01





SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973



For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A5 of A5

Report Version

: Rev. 01