





















GPS

Remove any GND planes (L2 - L whatever) below OSC. place OSC further from chip

Alternative TCXO: KT2016A26000ACW18TLG (541670-00) KYOCERA

