


## Appendix B. Setup Photographs

## <Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B1 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759B

Report Template No.: BU5-FR15CBT4.0 Version 1.0







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B2 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759B


Report Template No.: BU5-FR15CBT4.0 Version 1.0



Report No.: FR571759B

## <Radiated Emission>

LF



HF



## SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B3 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CBT4.0 Version 1.0