Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : A1 of A3
Report Issued Date : May 12, 2016
Report Version : Rev. 01

Report No.: FC611330

Report Template No.: BU5-FD15B Version 1.2





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : A2 of A3
Report Issued Date : May 12, 2016
Report Version : Rev. 01


Report Template No.: BU5-FD15B Version 1.2

Report No.: FC611330


<Radiated Emission>

Mode 3

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : A3 of A3
Report Issued Date : May 12, 2016
Report Version : Rev. 01

Report No.: FC611330

Report Template No.: BU5-FD15B Version 1.2