


Appendix C. Setup Photographs

<Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : C1 of C3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759C

Report Template No.: BU5-FR15CWL Version 1.0





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : C2 of C3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759C


Report Template No.: BU5-FR15CWL Version 1.0



Report No.: FR571759C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : C3 of C3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CWL Version 1.0