Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : A1 of A3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FC571759

Report Template No.: BU5-FD15B Version 1.2



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : A2 of A3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report Template No.: BU5-FD15B Version 1.2


Report No. : FC571759

CC Test Report No.: FC571759


<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : A3 of A3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report Template No.: BU5-FD15B Version 1.2