

Report No.: FR611330A

Appendix C. Setup Photographs

<Conducted Emission>



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : C1 of C3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : C2 of C3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR611330A

Report Template No.: BU5-FR15CBT Version 1.1




Report No.: FR611330A

<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : C3 of C3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1