Appendix A. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : A1 of A2
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No. : FR422550B

<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : A2 of A2
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: FR422550B