


Appendix B. Setup Photographs

<Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B1 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759A

Report Template No.: BU5-FR15CBT Version 1.0





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B2 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759A


Report Template No.: BU5-FR15CBT Version 1.0




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : B3 of B3
Report Issued Date : Apr. 28, 2016
Report Version : Rev. 02

Report No.: FR571759A

Report Template No.: BU5-FR15CBT Version 1.0