
3. **Internal Photograph of EUT**

Brand Name: iamplus / Model Name: IAM1110 / Marketing Name: dial

Report No.: EP571759




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Report Issued Date : Apr. 07, 2016 Report Version

: Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 11 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 12 of 28 Report Issued Date : Apr. 07, 2016

Report No.: EP571759

: Rev. 01 Report Version



Brand Name: iamplus / Model Name: IAM1110 / Marketing Name: dial 00 L 06 08 02 09 05 30 30 20


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110

: 13 of 28 Page Number Report Issued Date : Apr. 07, 2016

Report No.: EP571759

Report Version : Rev. 01

Report No.: EP571759



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 14 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01




Brand Name: iamplus / Model Name: IAM1110 / Marketing Name: dial 30 0,1 50

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 15 of 28 Report Issued Date : Apr. 07, 2016 Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 16 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01


Report No.: EP571759



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 17 of 28
Report Issued Date : Apr. 07, 2016

Report Version : Rev. 01


Report No.: EP571759



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 18 of 28
Report Issued Date : Apr. 07, 2016


Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 19 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01

Report No.: EP571759




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 20 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 21 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 22 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01


Report No.: EP571759




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 23 of 28
Report Issued Date : Apr. 07, 2016

Report Version : Rev. 01


Report No.: EP571759



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 24 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 25 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 26 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 27 of 28
Report Issued Date : Apr. 07, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1110 Page Number : 28 of 28 Report Issued Date : Apr. 07, 2016 : Rev. 01 Report Version