
3. Internal Photograph of EUT

Brand Name: iamplus / Model Name: IAM1010 / Marketing Name: PULS

Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 10 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550


Brand Name: iamplus / Model Name: IAM1010 / Marketing Name: PULS



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 11 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550


Brand Name: iamplus / Model Name: IAM1010 / Marketing Name: PULS



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 12 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01




Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 13 of 25 Report Issued Date : Jun. 16, 2014 Report Version : Rev. 01


Report No.: EP422550

Brand Name: iamplus / Model Name: IAM1010 / Marketing Name: PULS




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 14 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 15 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 16 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01


Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 17 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01




Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010




Report No.: EP422550




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 19 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 20 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 21 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 22 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 23 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 24 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01

Report No.: EP422550



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1010 Page Number : 25 of 25
Report Issued Date : Jun. 16, 2014
Report Version : Rev. 01