

Appendix E. Setup Photographs

<Conducted Emission>



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E1 of E3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR611330C

Report Template No.: BU5-FR15CWL Version 1.2







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E2 of E3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR611330C

Report Template No.: BU5-FR15CWL Version 1.2




Report No.: FR611330C

<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AB2S-IAM1111 Page Number : E3 of E3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.2