

## **DI** BLOCK ROCKER FLASH

iPA82



## CAUTION

RISK OF ELECTRIC SHOCK DO NOT OPEN



WARNING: SHOCK HAZARD - DO NOT OPEN AVIS: RISQUE DE CHOC ELECTRIQUE - NE PAS OUVRIR

WARNING: TO REDUCE THE RISK OF FIRE OR ELECTRIC SHOCK DO NOT EXPOSE THIS EQUIPMENT TO RAIN OR MOISTURE AVIS: NE PAS EXPOSER CE MATÉRIEL À LA PLUIE OU L'HUMIDITE AFIN DE REDUIRE LE RISQUE D'INFLAMMATION OU DE CHOC ELÉCTRIQUE

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1)THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.

In Denmark (Danmark): Apparatets stikprop skal tilsluttes en stikkontakt med jord, som giver forbindelse til stikproppens jord.

In Finland (Suomi): Laite on liitettävä suojakoskettimilla varustettuun nietoresiaan.

- In Norway (Norge): Apparatet må tilkoples jordet stikkontakt.
   In Sweden (Sverige): Apparaten skall anslutas till jordat uttag.

## Bluetooth\*

US Address: Ion Audio, LLC 200 Scenic View Dr. Cumberland, RI 02864 USA

EU Address: inMusic GmbH Harkortstr. 12-32 40880 Ratingen Germany



## Intertek 3043205

CONFORMS TO ANSI/UL STD, 60065 CERTIFIED TO CAN/CSA STD, C22,2 NO,60065





MADE IN CHINA

CAN ICES-3 (B)/NMB-3(B) FCC ID:2AB3E-IPA82 IC:10541A-IPA82



