



Page No. : 3 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018







Report No.: EP8N0134



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









Page No. : 5 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









Page No. : 6 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









Page No. : 7 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









Page No. : 8 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 9 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018









Page No. : 10 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018







-THE END-----

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 11 of 11
EP Report Version : Rev. 01
Issued Date : Dec. 11, 2018