


Appendix II - Test Setup Photos: AC Power Line Conducted Emission Test



2Report No.: TR-W1811-009 Page 50 of 71

FAX: +82-31-746-0800

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form_02 (Rev.0)
http://www.the-eng.co.kr





2Report No.: TR-W1811-009 Page 51 of 71

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form_02 (Rev.0)
http://www.the-eng.co.kr



Appendix III - Test Setup Photos: Radiated Emission Test



2Report No.: TR-W1811-009 Page 52 of 71

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form_02 (Rev.0)

http://www.the-eng.co.kr





2Report No.: TR-W1811-009 Page 53 of 71

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

http://www.the-eng.co.kr

Report Form_02 (Rev.0)





2Report No.: TR-W1811-009 Page 54 of 71

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form_02 (Rev.0)

http://www.the-eng.co.kr





2Report No.: TR-W1811-009 Page 55 of 71

FAX: +82-31-746-0800

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form_02 (Rev.0)

http://www.the-eng.co.kr