


## Appendix II - Test Setup Photos: AC Power Line Conducted Emission Test




Report No.: TR-W1807-009 Page 59 of 75

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form\_02 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr





2Report No.: TR-W1807-009

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form\_02 (Rev.0)


Page 60 of 75

TEL: +82-31-727-8300 FAX: +82-31-746-0800

http://www.the-eng.co.kr



## Appendix III - Test Setup Photos: Radiated Emission Test



2Report No.: TR-W1807-009 Page 61 of 75


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

FAX: +82-31-746-0800 <u>http://www.the-eng.co.kr</u>

Report Form\_02 (Rev.0)






2Report No.: TR-W1807-009 Page 62 of 75

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form\_02 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 <u>http://www.the-eng.co.kr</u>





2Report No.: TR-W1807-009 Page 63 of 75

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form\_02 (Rev.0)

http://www.the-eng.co.kr





2Report No.: TR-W1807-009 Page 64 of 75

FAX: +82-31-746-0800

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

TEL: +82-31-727-8300

Report Form\_02 (Rev.0)
<a href="http://www.the-eng.co.kr">http://www.the-eng.co.kr</a>