

Maysun Info Technology Co., Ltd 10th floor,B10 Building,Lilang Industrial Zone,Buji Town,Longgang District,Shenzhen.

Tel.: +86-755-88323763 Fax: +86-755-82780448

Attestation Letter

September 25, 2014

To: Bay Area Compliance Laboratories Corp. 1274 Anvilwood Avenue Sunnyvale, CA 94089

Dear Sir or Madam:

The RF chip, model: MT6166, installed in our product WCDMA mobile phone, model: LY Max 5.0; maysunm MID5005Lwhich supports EDGE functions. For using in North America and South America this chip will not support/enable the EDGE function. The EDGE function has been shielded by the manufacturer using the software.

Best Regards,

Sincerely,

Leon cai

Attestation Engineer