


SETUP PHOTOS 11.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





END OF REPORT

Page 144 of 144