


9. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION









BELOW 30MHz MEASUREMENT SETUP







POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB POWER ADAPTER





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH LAPTOP





END OF REPORT

Page 62 of 62