
SETUP PHOTOS 10.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION


















POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB AND LAPTOP





END OF REPORT