

# 10. SETUP PHOTOS


# ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




# RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)



Page 53 of 57




# **RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)**






# POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP



Page 55 of 57



# POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER



Page 56 of 57



**END OF REPORT**