


ANNEX C Internal photographs of the test sample




140344_pcb1

 Testengineer:
 Michael DINTER
 Report Number:
 F140344E1

 Date of issue:
 3 November 2014
 Order Number:
 14-110344
 page 1 of 2



ANNEX C Internal photographs of the test sample



140344_pcb2

 Testengineer:
 Michael DINTER
 Report Number:
 F140344E1

 Date of issue:
 3 November 2014
 Order Number:
 14-110344
 page 2 of 2