12 Vreeland Rd. Florham Park, New Jersey 07928, USA Tel: +1-937-593.7500

Fax: +1-937-593.7600

## Request for Class II Permissive Change

FCC ID: 2ABBQ9310B Data: July 10, 2014

## TO: Federal Communication Commission

Please be notified that we, the undersigned, Gerber Products Company (BabyNes US) declare that the reasons for this Class II permissive change are as below:

- Storage IC increase from 32M to 64M(just increase store volume).
- 2. PCB layout of power supply is changed(circuit diagram is same).
- 3. Main board layout is changed(circuit diagram is same).

Please refer to below form for detailed information:

2	Before	Now (Last Saturday Samples)	illustration
Hardw are	IC-MX25L <b>32</b> 06E M2I-12G,SOP-8	IC-MX25L <b>64</b> 06E M2I-12G,SOIC-8	<ol> <li>Storage IC increase from 32M to 64M</li> <li>No changed with the circuit diagram and number of pin for IC.</li> <li>SOIC-8 is correct. It's always the same as SOP-8. And no effect on SMT</li> </ol>

Thank you.

Sincerely

Daniel Roost / Director, Controlling, Systems & Operations, BabyNes US Gerber Products Company Inc.

Tel: +1-973-593.7613 Fax: +1-973-593.7600

Email: Daniel.roost@us.nestle.com