## Datascan, LP

2210 Hutton Drive, STE 100, Carrollton, TEXAS USA

Federal Communications Commission 7345 Oakland Mills Road Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: FCC ID: 2ABDLABO

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by Datascan,LP will establish a new FCC ID for the purpose of marketing.

The original grant to Datascan,LP with FCC ID:2ABDLQPID1000 will remain in effect.

Per 2.933(b)

- 1.) The original identification is: FCC ID:2ABDLQPID1000
- 2.) The original granted date is: 12/01/2013
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

Devin arnold

- Cover Letter
- External Photos
- ID Lable and Location Info

Sincerely

Client's name / title: Kevin Arnold / Director

Contact information / address: 2210 Hutton Drive, STE 100, Carrollton, TEXAS USA

Contact Email: kevin.arnold@datascan.com

ContactPhone: +1 214 351 4848 ContactFax: +1 214 284 3980