
Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABDW-1229 Page Number : 1 of 2
Report Issued Date : Sep. 23, 2015
Report Version : Rev. 01


Report No.: FR542541A

Report Template No.: BU5-FR15CBT Version 1.0


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABDW-1229 Page Number : 2 of 2
Report Issued Date : Sep. 23, 2015
Report Version : Rev. 01

Report No.: FR542541A

Report Template No.: BU5-FR15CBT Version 1.0