

Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABDW-1229 Report No. : FR542541D
Report Version : Rev. 01
Page Number : 1 of 2

Report No.: FR542541D

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.0




Report No.: FR542541D

<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABDW-1229 Report No. : FR542541D Report Version : Rev. 01 Page Number : 2 of 2

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.0