Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABGCPT2 Page Number : A1 of A2
Report Issued Date : Sep. 26, 2014
Report Version : Rev. 01


Report No. : FR473003A

Report Template No.: BU5-FR15CBT Version 1.0


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABGCPT2 Page Number : A2 of A2
Report Issued Date : Sep. 26, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0

Report No.: FR473003A