



## 4.6 Test Photographs



Front View



Rear View

Cerpass Technology Corp.

Tel:886-2-2655-8100 Fax:886-2-2655-8200


Issued Date : Nov. 04, 2013

Report No.: TEFB1310152


Page No. : 19 of 98 FCC ID. : 2ABH8C201



## 5.8 Test Photographs (30MHz ~ 1GHz)



Front View



Rear View

Cerpass Technology Corp.

Tel:886-2-2655-8100 Fax:886-2-2655-8200


Issued Date : Nov. 04, 2013

Report No.: TEFB1310152


Page No. : 52 of 98 FCC ID. : 2ABH8C201



## 5.9 Test Photographs (1GHz ~ 25GHz)



Front View



Rear View

Cerpass Technology Corp.

Tel:886-2-2655-8100 Fax:886-2-2655-8200

Issued Date : Nov. 04, 2013

Report No.: TEFB1310152

Page No. : 53 of 98 FCC ID. : 2ABH8C201