



FCC Test Report No.: EP3D0631






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B3 OF B10
ISSUED DATE : Feb. 19, 2014











SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B4 OF B10
ISSUED DATE : Feb. 19, 2014



FCC Test Report No.: EP3D0631







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B5 OF B10
ISSUED DATE : Feb. 19, 2014











TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B10 ISSUED DATE : Feb. 19, 2014










TEL: 886-3-327-3456 FAX: 886-3-327-0973









TEL: 886-3-327-3456 FAX: 886-3-327-0973