

Appendix A. Test Photos

Report No. : FR3D0631-01

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report No.: FR3D0631-01

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR3D0631-01

SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report No.: FR3D0631-01

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6


Report Version

: Rev. 01



FCC Test Report No.: FR3D0631-01

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report

Report No. : FR3D0631-01

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01