12/15/2014

Equipment Autorisation Division Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Subject: Class II permissive change Request

FCC ID: 2ABKZ-GC791903 Granted on: 01/06/2014

To whom may concern:

Pursuant to CRF Section 2.1043, Shenzhen TongFang Information Technologies CO.,LTD requests a Class II permissive change

Change the card reader of the product.

The card reader is connected to the tablet through the earphone jack.

The differences between the two kinds of card reader:

- 1. The size and shape of the two kinds of card reads readers are different.
- 2. The new card reader replaced to the previous card reader, and the new card reader has the Europay Mastercard Visa function.

The front view of the previous card reader:



The front view of the new card reader:




The back view of the previous card reader:



The back view of the new card reader:

Shenzhen TongFang Information Technologies CO.,LTD Floor3, Building D, TongFang Information Harbour, LangShan Road, NanShan, Shenzhen, China



All of above changes are not relative to the RF circuit.

And, the change do not affect all the RF parameter, function and output power.

Dated this		Day of 12/15/2014	
Ву:	Mach	rang	Mick Wang
	Sig	nature	Printed
Title:	Quality	management representativ	<u>e</u>
On behalf o	of:	Shenzhen TongFar Information Technolo CO.,LTD	
Tolonhono		196 755 22010100	