

External photographs of equipment under test

Top with shield



Shield removed



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

**Elecsys International Corporation** 

Model: 02-0084-10

Test #: 180820 Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

File: 02008410 ExtPho


S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410

Page 1 of 4

## **Bottom**





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

**Elecsys International Corporation** 

Model: 02-0084-10 Test #: 180820

File: 02008410 ExtPho


Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

S/N: ENG1

FCC ID: 2ABOY-02008410 IC: 12222A-02008410

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

**Elecsys International Corporation** 

Model: 02-0084-10 Test #: 180820


Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

Page 3 of 4 File: 02008410 ExtPho

S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Elecsys International Corporation S/N: ENG1

Model: 02-0084-10 FCC ID: 2ABOY-02008410 Test #: 180820 IC: 12222A-02008410

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

File: 02008410 ExtPho Page 4 of 4