

Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Elecsys International Corporation

Model: 02-0084-10 Test #: 180820

File: 02008410 TSup

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

S/N: ENG1

FCC ID: 2ABOY-02008410 IC: 12222A-02008410

Page 1 of 11





Elecsys International Corporation

Model: 02-0084-10 Test #: 180820

File: 02008410 TSup

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

S/N: ENG1

FCC ID: 2ABOY-02008410 IC: 12222A-02008410

Page 2 of 11





Elecsys International Corporation


Model: 02-0084-10 Test #: 180820

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018 File: 02008410 TSup

S/N: ENG1 FCC ID: 2ABOY-02008410 IC: 12222A-02008410

Page 3 of 11





Elecsys International Corporation

Model: 02-0084-10 Test #: 180820

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

File: 02008410 TSup


S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410

Page 4 of 11





Elecsys International Corporation S/N: ENG1
Model: 02-0084-10 FCC ID: 2ABOY-02008410

Model: 02-0084-10 Test #: 180820

Test #: 180820 IC: 12222A-02008410 Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

File: 02008410 TSup Page 5 of 11





Elecsys International Corporation

Model: 02-0084-10 Test #: 180820


Test #: 180820 IC: 12222A-02008410 Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

S/N: ENG1

FCC ID: 2ABOY-02008410

File: 02008410 TSup Page 6 of 11





Elecsys International Corporation

Model: 02-0084-10

Test #: 180820 Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

Page 7 of 11 File: 02008410 TSup

S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410





Elecsys International Corporation

Model: 02-0084-10 Test #: 180820

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

Page 8 of 11 File: 02008410 TSup

S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410





Elecsys International Corporation S.

Model: 02-0084-10 Test #: 180820


Test to: CFR47 15.249, RSS-210, RSFile: 02008410 TSup

S/N: ENG1 FCC ID: 2ABOY-02008410 IC: 12222A-02008410

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018

Page 9 of 11





Elecsys International Corporation

Model: 02-0084-10 Test #: 180820

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018 File: 02008410 TSup

S/N: ENG1

FCC ID: 2ABOY-02008410

IC: 12222A-02008410

Page 10 of 11



Elecsys International Corporation S/N: ENG1

Model: 02-0084-10 FCC ID: 2ABOY-02008410 Test #: 180820 IC: 12222A-02008410

Test to: CFR47 15.249, RSS-210, RSS-Gen Date: September 17, 2018 File: 02008410 TSup Page 11 of 11